



Date Created: 1/23/2004
Date Issued: 2/2/2004
PCN # 20040406

INFORMATION ONLY NOTIFICATION

This is to inform you that a minor change is being made to the following product(s). This notification is for your information only.

Updated process quality documentation, such as FMEAs and Control Plans, are available for viewing upon request.

If you have any questions concerning this change, please contact:

Name: Marcellino, John G.
E-Mail: John.Marcellino@notes.fairchildsemi.com
Phone: 408-822-2552

PCN Originator

Name: Principi, Fabio E.
E-mail: Fabio.Principi@notes.fairchildsemi.com
Phone: 408 822 2565

REL Engineer

Name: Jose, Maggie
E-mail: Maggie.Jose@notes.fairchildsemi.com
Phone: 1-408-822-2329

PCN Type: Metallization Mask Revision

Effectivity

Expected 1st Device Shipment Date: 3/1/2004
Earliest Year/Work Week of Changed Product: 0410
(Note: Package marking may differ from this format)

Product ID (Description):

This notification applies to the FAN5098MTC product: Two Phase Interleaved Synchronous Buck Controller for AMD's CPU..

Description of Change:

The metallization change has been made to improve the parametric yield of the OC (Over-Current) test.

This change has no effect on the performance of the FAN5098MTC in the intended application and the specifications in the current data sheet are not changed.

Affected FSIDs
FAN5098MTC

FAN5098MTCX