

## Appendix C

### Products To Be Supported For Up To Six Months

|                        |                      |                    |
|------------------------|----------------------|--------------------|
| RFD20N03SM9A_R4805     | 100314QCX_QF075      | FDS3570_Q          |
| TO252SHT_R4963         | 74LCX157MTCX_Q       | FDB6670AL_Q        |
| HUFA75309P3_S2565      | 74F245SJ_Q           | NDS335N_Q          |
| HUFA76407D3ST_QF085    | 74VHC74MX_Q          | FDP6030BL_Q        |
| HUF75307D3ST_SB78016   | NC7S00P5X_Q          | FDC6305N_Q         |
| HUFA76419D3ST_S2300    | MM74HC273N_QF014     | MMBF170_Q          |
| ISL9V3040D3ST_Q        | 74F244PC_Q           | FDS5670_Q          |
| RFD3055LESM9A_R4280    | 74ACT258SCX_Q        | FDC655AN_Q         |
| FGD3N60LSDTM_SB82092   | 74LVTH2244MTCX_Q     | FDC6323L_Q         |
| RFD8P06LESM9A_R4407    | 74ACT00SCX_Q         | FDS6570A_Q         |
| TO220BLANK_QF062       | 74F138SJX_Q          | SI4410DY_Q         |
| HGTP12N60A4D_QF085     | 74LVX3245QSCX_Q      | FDR4420A_Q         |
| HUF76639S3ST_R4882     | 74VHC00MX_Q          | NDS8410A_Q         |
| ISL9V5036S3ST_SB82065  | DM74ALS540ASJX_Q     | BSS84_Q            |
| HUFA76419D3ST_QF085    | 74ACT521SCX_Q        | NDS9945_Q          |
| RFD3055LE_R4769        | 74AC244PC_Q          | FDG6318P_Q         |
| TO263SHT_R4963         | 74LCX07MX_Q          | FDG6313N_Q         |
| RURP3060_SB82069       | NC7WZ126K8X_Q        | FDC6312P_Q         |
| TO220BLANK_QF089       | NC7SZ374P6X_Q        | NDC7001C_Q         |
| HUFA76619D3ST_S2565    | 74LVX541MTCX_Q       | FDN335N_Q          |
| FDB3672_SB82072        | 74VHC138MX_Q         | FDR840P_Q          |
| HGT1S14N37G3VLS_R4662  | 74ALVC16244GX_Q      | FDN302P_Q          |
| FDN5618P_SB4N007       | 74ALVC16245GX_Q      | NDS9407_Q          |
| RFD3055LE_R4470        | CD4016BCMX_SF501560  | NDS8434A_Q         |
| RFP40N10LE_R4366       | MM74HC4052MX_Q       | FDC6506P_Q         |
| NDS351AN_SBNL001       | NC7ST08P5X_Q         | FDW2502P_QF40      |
| HUFA76407DK8T_QF085    | 74ACT244SJX_Q        | HUF75631SK8T_S2075 |
| HUFA76407D3ST_S2565    | 74ACT241SCX_Q        | FDC6420C_Q         |
| HUF75345P3_R4743       | 74LCX38SJX_Q         | FDC6330L_Q         |
| RFD20N03SM9A_R4770     | 74LCX08MX_Q          | FDD6682_Q          |
| HGTP14N40F3VL_R4600S   | 74ABT244CSCX_Q       | FDC653N_Q          |
| ISL9V3040S3ST_Q        | CD40106BCMX_Q        | FDB6035AL_Q        |
| 73389_Q                | 100331QCX_Q          | FDS6894A_Q         |
| RFD3055LESM9A_SB82064  | 74LCX32MX_Q          | FDN338P_Q          |
| HUF76633P3_R4883       | 74F74SJ_Q            | NDS9956A_Q         |
| HUF76437S3ST_R4908     | 74LVX125MX_Q         | NDS9430A_Q         |
| HUFA75307T3ST_Q        | NC7SZU04P5X_Q        | FDS6679_Q          |
| HUF75321D3ST_S2457     | 74LCX138MTCX_Q       | BSS123_Q           |
| HUF75339S3ST_R4935     | GTLP16617MTDX_Q      | FDN5630_Q          |
| FDT459N_B3E005A        | 74VHC86MTCX_SF500949 | FDS6574A_Q         |
| FDC642P_SB4N006        | 74F163APC_Q          | FDW2506P_Q         |
| RFD8P06LESM9A_R4490    | 74ACTQ244QSCX_Q      | FDD6685_Q          |
| TO247SHT_R4963         | 74ACTQ08SCX_Q        | FDN5618P_Q         |
| 73282_Q                | 74LCX245MTCX_QF40    | FDW9926A_QF40      |
| ISL9V3040S3ST_R4956    | 74F00SJX_Q           | FDD6690A_Q         |
| HUFA76419D3ST_SB82041A | 74AC139SCX_Q         | 5MS1_B5M002C       |
| RHRP860_R4647          | 74VHC244MTCX_Q       | FDG6318PZ_Q        |
| NDT014L_SB9D008        | 74AC521SCX_Q         | NDS9410A_Q         |
| FDP3682_SB82034        | 74F373SJX_Q          | FDD3570_Q          |
| HGT1S14N41G3VLS_R4875  | 74LCX00MX_Q          | FDN340P_Q          |
| FDD16AN08A0_SB82033A   | DM74ALS245AWMX_Q     | NDS9936_Q          |

|                        |                      |                  |
|------------------------|----------------------|------------------|
| HUFA75639S3ST_S2457    | 74ABT899CQCX_QF075   | FDS9926A_Q       |
| HUFA76419P3_S2565      | 74LCX32SJX_Q         | MTD3055VL_Q      |
| HUF75333P3_S2515       | NC7WZ240K8X_Q        | FDS6375_Q        |
| FDS6975_SBAM003        | 100341QCX_SF88045A   | FDD6030L_QF080   |
| ISL9V5036S3ST_QF058    | 74LCX573MTCX_Q       | FDN327N_Q        |
| HUFA75343P3_QF085      | 74F74SCX_SF86273A    | NDS9430_Q        |
| ISL9V5036S3ST_SB82031B | 74ACT251SCX_Q        | FDG6335N_SBX002  |
| FFB20UP20DN_SB82117    | CD4013BCMX_Q         | FDP6670AL_Q      |
| HUF76419S3ST_R4908     | 74LCX841MSAX_Q       | FDN339AN_Q       |
| BSS138_SB9G001         | 74LVX32MX_Q          | FDS6694_Q        |
| FDP42AN15A0_SB82024A   | 74VHC125MX_Q         | FDGS2P102A_QF065 |
| RURD620CCS9A_R4870     | 74VHC14MTCX_Q        | FDGS2P106A_Q     |
| ISL9V3040D3ST_R4969    | 74VHCT540AMTCX_Q     | NDT3055L_Q       |
| ISL9N312AD3ST_SB82067  | DM74ALS640AWMX_Q     | FDD5670_Q        |
| FDD120AN15A0_W82016B   | 74ACT825SCX_Q        | FDD5690_Q        |
| FDD24AN06LA0_SB82060   | NC7SZ57P6X_Q         | FDS8433A_Q       |
| ISL9V5036S3_Q          | 74AC161SCX_Q         | SI9424DY_Q       |
| HUFA76404DK8T_SB82047  | MM74HC589MX_SC161337 | FDC5614P_Q       |
| RURD620S9A_S2457       | DM74ALS163BMX_Q      | FDS9412_Q        |
| FDB20AN06A0_B82014A    | 74F74SJX_Q           | NDS0610_Q        |
| HUF75321S3ST_R4908     | 74F244SCX_Q          | NDS7002A_Q       |
| HUFA76429D3ST_QF085    | 74LCX257MTCX_Q       | FDT458P_Q        |
| HUFA75321D3ST_Q        | 74LCX02MTCX_Q        | FDS4465_Q        |
| HUFA75344G3_SB82096    | 74AC20SCX_Q          | NDS355AN_Q       |
| HUF76429D3ST_S2457     | 74LVX244MX_SF501628  | FDZ206P_Q        |
| RURD660S_R4812         | MM74HCT244MTCX_Q     | FDW258P_Q        |
| HUF76407DK8T_R4810     | NC7S02M5X_Q          | FDG6303N_Q       |
| HUF76629D3ST_R4885     | 74LCX32245GX_Q       | FDD6680A_Q       |
| ISL9V2040S3ST_SB82063  | 74F74SCX_Q           | FDV304P_Q        |
| HUF76129D3ST_S2515     | 74LCX16374MTDX_Q     | FDN304P_Q        |
| HUF76409D3ST_R4921     | 74LVX244MTCX_Q       | FDGS6N303_Q      |
| HUFA76409T3ST_B76004A  | MM74HC154WMX_Q       | FDS6680_Q        |
| HUF76432S3ST_R4908     | 74ACTQ32SCX_SF500570 | FDW2502P_Q       |
| HUFA75344S3ST_R4966    | NC7SV157P6X_Q        | FDC6401N_Q       |
| ISL9V3040D3ST_SB82019B | 74F273SCX_Q          | FDC6561AN_Q      |
| FDSS2407_SB82086       | NC7SZ02P5X_Q         | FDC6301N_Q       |
| FDSS2407_SB82097       | 74F280PC_Q           | FDN306P_Q        |
| HUFA76633S3ST_S2575    | NC7SZ05M5X_Q         | FDD6612A_Q       |
| ISL9V5036S3_SB82032A   | 74VHC273MTCX_Q       | FDC6310P_Q       |
| RFD14N05LSM9A_S2515    | 74AC04SCX_Q          | FDS6612A_Q       |
| ISL9V3040S3ST_SB82020A | GTLP8T306MTC_Q       | FDS6986S_Q       |
| SI4467DY_SBAA005A      | 74AC10SCX_Q          | FDC604P_Q        |
| HUFA75852G3_SB82025A   | 74ACT373SCX_Q        | FDC5612_Q        |
| ISL9V3036S3ST_SB82029A | 74LVTH244MTCX_Q      | FDC633N_Q        |
| HUF75637S3ST_S2551     | 74LVTH646MTCX_Q      | FDS6930A_Q       |
| HUFA76409D3ST_R4974    | 74F32SCX_Q           | FDD8880_QF080    |
| ISL9V3036D3ST_R4970    | 74VHC573MX_Q         | FDS6912A_Q       |
| RFD3055LESM9A_R4383    | MM74HC4538N_Q        | FDG6304P_Q       |
| HGT1S20N36G3VLS_R4737  | 74ACT174SCX_Q        | FDS6294_Q        |
| ISL9V3040D3ST_B49006A  | 74AC244MTCX_Q        | FDG6335N_Q       |
| HUFA76409D3ST_B76008A  | 74VCX162244MTDX_Q    | FDB8030L_Q       |
| FDB2532_SB82023A       | 74F521SCX_Q          | FDC6333C_Q       |
| RHRD660S9A_S2515       | CD4013BCMX_SC161380  | NDS351AN_Q       |
| HUFA76404DK8T_SB82040A | 74F38SJ_Q            | FDD8870_Q        |
| HUFA76413DK8T_B76001A  | 74AC299SCX_Q         | FDV301N_Q        |

|                          |                       |                      |
|--------------------------|-----------------------|----------------------|
| FDB42AN15A0_SB82021A     | 74VHC32MX_Q           | FDT3612_Q            |
| ISL9V3040S3ST_R4975      | 74F08SCX_Q            | FDS3672_Q            |
| HUF75639S3ST_S2515       | 74ACTQ04SCX_Q         | FDB7030BL_Q          |
| HUF75344S3ST_S2457       | NC7WZ32K8X_Q          | FDS9435A_Q           |
| ISL9V2040S3ST_B9V002B    | 74VHC245MX_Q          | FDN361AN_Q           |
| HUF76633S3ST_R4884       | 74LCX04MX_Q           | FDS6575_Q            |
| ISL9V3040S3ST_R4969      | 74LVX125MTCX_Q        | FDC2512_Q            |
| HGT1S14N40G3VLS_R4788    | MM74HC251MX_Q         | FDC654P_Q            |
| HGT1S7N60A4DS9A_R4921    | 74LCX14MTCX_QF40      | FDU8896_QF071        |
| HUF76409D3ST_S2457       | 74LVX244MX_Q          | 2N7002_Q             |
| HGT1S20N36G3VL_SB82039A  | 74LCX541MTCX_Q        | FDN357N_Q            |
| HGT1S20N36G3VLS_SB82038A | 74ACT74SCX_Q          | NDS352AP_Q           |
| ISL9V3040D3ST_R4940      | 74ACT821SCX_Q         | FDB6670AL_QM         |
| ISL9N302AS3ST_QF059      | 74VHC161MTCX_Q        | FDS6990A_Q           |
| ISL9V3040D3ST_R4956      | NC7SV04P5X_Q          | FDD6670A_Q           |
| IRFW644BTM_AS003         | 74LCX245WMX_Q         | FDS6680A_Q           |
| HUF75345P3_R4908         | 74F280SCX_SF86335A    | FDC634P_Q            |
| HUF75329D3ST_R4820       | 74VHC132MTCX_Q        | NDC7002N_Q           |
| HUF76419D3ST_R4921       | 74AC11SCX_Q           | FDC638P_Q            |
| ISL9V5036S3ST_R4971      | 74VHC595MX_Q          | FDC637AN_Q           |
| FDB070AN06A0_Q           | 100314QCX_Q           | FDD3706_Q            |
| RFD14N05_Q               | 74ABT125CSCX_Q        | FDS4672A_Q           |
| RURG80100_Q              | 74LCX06MTCX_Q         | FDW256P_Q            |
| HUF75645S3S_Q            | 74ACTQ245SCX_Q        | FDG6322C_Q           |
| SF9154PWD_NP             | MM74HC574WMX_Q        | FDN337N_Q            |
| HUF75639S3ST_Q           | 74F14SCX_Q            | FDS6670A_Q           |
| HUF75339P3_Q             | NC7SZ00P5X_Q          | NDT456P_Q            |
| FQ13N50PWD_NP            | 74VHCT245ASJX_Q       | FDS6975_Q            |
| HUF75321P3_Q             | NC7SP34P5X_Q          | FDB7045L_Q           |
| FDD16AN08A0_Q            | CD4066BCMX_Q          | FDS6680A_SBNM001A    |
| HUF75329D3_Q             | 74AC74SCX_Q           | SI4463DY_Q           |
| FGS15N40LTF_Q            | CD4052BCMX_Q          | FDS6690A_Q           |
| IRF840B_Q                | 74LCX38MX_Q           | FDG6306P_Q           |
| HUF75321D3ST_Q           | 74LCX244WMX_Q         | FDB6035AL_QM         |
| HGTG40N60B3_Q            | 74AC05SCX_Q           | FDG6301N_Q           |
| FDP060AN08A0_Q           | 74VHC00MTCX_Q         | FDS6680S_Q           |
| HRF3205_Q                | 74LCX07MTCX_Q         | FDD6512A_QF080       |
| HUF75842P3_Q             | NC7WZU04P6X_Q         | FDZ298N              |
| RHRG3060_Q               | 74LCX138MX_Q          | FDN336P_Q            |
| RFD16N05SM9A_Q           | MM74HC161MX_Q         | FDS9431A_Q           |
| HUF75344P3_Q             | DM74ALS244AWMX_Q      | FDS6900S_SB5E024A    |
| RURG3060_Q               | 74LCX16821MEAX_Q      | FDZ298N_Q            |
| HUF75307D3ST_Q           | DM74ALS08MX_Q         | FDS7760A_Q           |
| RFP3055LE_Q              | MM74HC4051WMX_Q       | FDG6323L_Q           |
| HUF75637P3_Q             | 74AC245SCX_Q          | FDZ299P_Q            |
| RHRP860_Q                | 74AC02SCX_Q           | BSS138_Q             |
| RHRG5060_Q               | DM74ALS244AMSAX_Q     | FDS6688_Q            |
| HUF76419D3ST_Q           | 74ACTQ240SCX_Q        | FDS8928A_Q           |
| HUF75345P3_Q             | 74F163ASCX_Q          | NDS332P_Q            |
| RFD3055LESM9A_Q          | 74LCX74MX_Q           | FDD14AN06LA0_SB82116 |
| HUF75842S3ST_Q           | 74LVTH125MX_Q         | FDS6682_Q            |
| PCG20N60B3W              | NC7NZ14K8X_Q          | FDC642P_Q            |
| HUF75542P3_Q             | 74LCX00MTCX_Q         | FDS6912_Q            |
| HUF75333S3ST_Q           | 74VHC175MTCX_SF501629 | FDS4410_Q            |
| HGTG20N60A4_Q            | 74VHC08MX_Q           | NDT014L_Q            |

FDP20AN06A0\_Q  
FDH44N50\_SW82046A  
FDP2532\_Q  
FDD10AN06A0\_Q  
HUF75321P3\_S2552  
RHRP15120\_Q  
HGTG18N120BND\_Q  
RFP70N06\_Q  
HGTG30N60B3\_Q  
HUF76429D3ST\_Q  
FDB3652\_Q  
FQD2N100TM\_Q  
HGTP12N60A4D\_Q  
RURG3060CC\_Q  
HUF75637S3\_R4895  
HUF75645S3ST\_Q  
RFD14N05SM9A\_Q  
ISL9R3060G2\_Q  
RHRP1560\_Q  
HGT1S10N120BNST\_Q  
HUF75229P3\_Q  
HUF76419S3ST\_Q  
HUF76429S3ST\_Q  
FDB2532\_Q  
RFD14N05LSM9A\_Q  
HUF75344G3\_Q  
RFD3055LE\_R4821  
HGTG40N60B3\_R4964  
FGA50N100BNTDTU\_SBXD001  
HUF75652G3\_Q  
HGTP12N60C3D\_R4900  
HUF75333P3\_S2552  
HUF75332P3\_S2543  
HUF75639P3\_Q  
BUZ11\_R4941  
HUF75545P3\_R4932  
HUF75339P3\_S2552  
HGT1S2N120CN\_R4977  
HUF76143P3\_S2552  
HUF76139P3\_S2552  
HUF75345P3\_S2552  
FQA62N25CPWD  
FIN1031M\_Q  
74VHC161284MTDX\_Q  
74VHC161284MEAX\_Q  
FIN1531MX\_Q  
FIN1532M\_Q  
FIN1032MX\_Q  
FIN1048M\_Q  
FIN3385MTDX\_Q  
FIN1002M5X\_Q  
FIN1017MX\_Q  
FIN1001M5X\_Q  
USB1T11AMX\_Q  
74LVX161284MEAX\_Q

74VHC138MTCX\_Q  
MM74HCT164MX\_Q  
74F652SCX\_Q  
74AC32SCX\_Q  
CD4021BCMX\_Q  
74ABT543CSCX\_Q  
NC7WZ02K8X\_Q  
NC7WZ241K8X\_Q  
MM74HC123AMX\_Q  
74LCX541SJX\_Q  
74F899QCX\_SF87525A  
74ACTQ16244SSCX\_Q  
74ACTQ273SCX\_Q  
CD4051BCMX\_Q  
NC7WZ132K8X\_Q  
74VCX16245MTDX\_QF40  
FXLP34P5X\_Q  
NC7SZ19P6X\_Q  
74LCX245SJX\_Q  
74ACT08SCX\_Q  
74AC125SCX\_Q  
74LCX16245MTDX\_Q  
74LVT245WMX\_Q  
MM74HC688WMX\_SF501676  
74AC541SCX\_Q  
74LCX126MTCX\_Q  
74ACT163SCX\_Q  
74LCX157MX\_Q  
74AC273SCX\_Q  
74ABT16501CSSCX\_Q  
NC7ST08M5X\_Q  
74VHCT573AMTCX\_Q  
74VHC08MTCX\_Q  
MM74HC373MTCX\_Q  
NC7SZ157P6X\_Q  
NC7S86M5X\_Q  
74VHC02SJX\_Q  
74LCX14MX\_Q  
74ACT125MTCX\_Q  
74AC00SCX\_Q  
74LCX00SJX\_Q  
74AC245MTCX\_Q  
NC7S14M5X\_Q  
74LCX541MTCX\_QF086  
DM74ALS74AMX\_Q  
74LCX86MTCX\_Q  
74LCX373MSAX\_Q  
74VHCT245AMTCX\_Q  
NC7SZ32P5X\_Q  
74LCX162244MTDX\_QF40  
NC7NZ34K8X\_Q  
74LVX3245WMX\_Q  
74LVX4245MTCX\_SF501627  
74LCX38MTCX\_Q  
74ABT541CSCX\_Q

FDT434P\_Q  
FDD6296\_Q  
FDS4435A\_Q  
FDS7788\_Q  
NDS331N\_Q  
FDV303N\_Q  
FDS6898A\_Q  
FDC658P\_Q  
FDS6990A\_SBBM005B  
FDZ5047N  
FDG6306P\_SBGX002  
FDU8896\_SBSW002A  
FDU8896\_Q  
FDC640P\_Q  
FDG6331L\_Q  
FDS6692\_SBDM001A  
FDC655AN\_SB5E020A  
FDU6680\_Q  
FDD6680\_Q  
FDD8896\_Q  
FDS6986S\_SBBM006B  
FDS8958A\_SB5E019A  
FDZ299P  
FDG6332C\_Q  
FOD817X\_5698D  
74OL6000\_Q5693D  
ML4824CS2X\_Q  
FAN4810MX\_Q  
ML4800ISX\_Q  
ML4812CQX\_Q  
FAN4810N\_Q  
ML4824CP1\_Q  
ML4800CSX\_Q  
ML4812IQX\_Q  
FAN8024CDTF\_Q  
NZT44H8\_Q  
NZT45H8\_Q  
BCP56\_Q  
WZD4\_FZVW004A  
MBRS320\_Q  
BCW69\_Q  
GF1G\_Q  
XZD4\_FZXZ004A  
FFB3904\_Q  
FZTZ005A\_QF084  
BAR43S\_Q  
SMBJ12A\_Q  
6192\_T61001C  
BSR14\_Q  
BAV21\_QT50A  
MMSZ5245B\_Q  
MMBT2369\_Q  
6892\_T68011A  
SS25\_Q  
6892\_T68057D

74F377SCX\_Q  
MM74HC4060N\_Q  
74ACT399SCX\_Q  
74VHC163MTC\_QF40  
CD4066BCMX\_SF501402  
MM74HCT04MX\_Q  
DM74ALS74AMX\_SD108156  
74LCX11MTCX\_Q  
74VHCT244ASJX\_Q  
74LCX08SJX\_Q  
74F163ASJX\_Q  
74F125PC\_Q  
MM74HC573WMX\_Q  
DM74ALS374N\_Q  
74F240SJ\_Q  
74F14PC\_Q  
74ACT74SJ\_Q  
74F112SJX\_Q  
74F377SCX\_SF500841  
74ABT245CSJX\_Q  
74ACT175SCX\_Q  
74VHC373MTCX\_QF40  
74LVT2244MTC\_Q  
74AC138SCX\_SF501499  
74LVQ14SCX\_Q  
74LVX74MX\_Q  
MM74HCT00N\_Q  
74LCX240SJX\_Q  
MM74HC08N\_Q  
NC7SZ32P5X\_QF40  
74LCX125MX\_Q  
MM74HC574SJX\_Q  
DM74ALS10AMX\_Q  
74VHC153MTCX\_Q  
74F109SJX\_Q  
74F112SCX\_SF86277A  
NC7S32P5X\_QF40  
74F161ASCX\_Q  
NC7WZ38K8X\_Q  
74VHC00MTCX\_QF40  
NC7SZ04M5X\_QF40  
74VHCT240AMTCX\_Q  
NC7SU04P5X\_Q  
MM74HCT245WMX\_Q  
74LVT245MTCX\_Q  
74F02SJX\_Q  
CD4093BCN\_Q  
MM74HC138MTCX\_QF40  
74ABT125CSCX\_SF500917  
NC7SZ125P5X\_SF500964  
74LVTH573MTCX\_Q  
74VHCT245AMTCX\_QF40  
MM74HC4514WMX\_Q  
74F86SJX\_Q  
74F38SCX\_Q

74LCX08MTCX\_Q  
NC7SZ05P5X\_Q  
MM74HC00MX\_Q  
74ACT109SCX\_Q  
74LCX244MTCX\_QF40  
74VHC374MTCX\_Q  
NC7SZ126P5X\_Q  
74LVTH162244G\_Q  
MM74HC04MX\_SC162353  
74AC574SCX\_Q  
100302QCX\_SF88047A  
NC7S32M5X\_Q  
74AC138SCX\_Q  
NC7SZ126M5X\_Q  
NC7SZ32M5X\_Q  
NC7SZ373P6X\_Q  
MM74HC4066MX\_Q  
NC7SZ74K8X\_Q  
74LCX04MTCX\_Q  
74VHC14MX\_Q  
100325QCX\_Q  
NC7SZ04P5X\_Q  
74ACTQ00SCX\_Q  
SCAN18540TSSCX\_Q  
74ACT138SCX\_Q  
74AC14SCX\_Q  
MM74HC14MX\_Q  
NC7ST04P5X\_Q  
MM74HC4051MX\_Q  
74LCX240MSAX\_Q  
74LVTH162245GX\_Q  
74ACT244SCX\_Q  
74F646SCX\_Q  
74AC244SCX\_Q  
MM74HCT00MX\_Q  
NC7S86M5X\_SF501630  
DM74ALS03BMX\_Q  
MM74HC132MX\_Q  
NC7SZ02M5X\_Q  
NC7S08P5X\_Q  
100324QCX\_Q  
MM74HC244WMX\_QF086  
NC7SZ175P6X\_Q  
MM74HC08MX\_Q  
74LCX244MSAX\_Q  
NC7SU04M5X\_Q  
74ALVCF322835GX\_Q  
NC7NZ17K8X\_Q  
SCAN18245TSSCX\_Q  
74ACTQ244SCX\_Q  
CD4538BCMX\_Q  
74LCX32MTCX\_Q  
74VHC573MTCX\_Q  
74VHC86MTCX\_Q  
NC7S04M5X\_Q

ES1B\_Q  
MMBTA42\_Q  
MMBZ5232B\_Q  
MMBD914\_Q  
1N4740ATR\_Q  
MMBTA55\_Q  
P6KE200A\_Q  
MMBD4148CA\_Q  
PZTA64\_Q  
SMBJ5V0A\_Q  
MMBT5087\_Q  
FMBM5551\_SB16001  
PZTA14\_Q  
FDLL4150\_Q  
BSR16\_Q  
BZX84C5V6\_Q  
MMSZ4689\_Q  
SMBJ58A\_Q  
BAV20TR\_Q  
S1G\_Q  
BAS19\_Q  
BCW71\_Q  
MMBT5179\_Q  
MMBT5550\_Q  
1992\_X19166B  
BAS16\_Q  
SMBJ20A\_Q  
BZX84C3V9\_Q  
MMBD7000\_Q  
0749\_B07722A  
SMCJ20A\_Q  
BAW56\_Q  
7899\_X78070A  
MMBD4148SE\_Q  
FFB2907A\_Q  
3K49\_FDSS539C  
MMBT5401\_Q  
1N5818\_Q  
MMSD914\_Q  
DF06S\_Q  
6392\_X63807A  
1V5KE20A\_Q  
1349\_B13145C  
MMBTA56\_Q  
BAV23S\_Q  
MMBT5551\_Q  
MMSZ5242B\_Q  
MMBT3906\_Q  
MBR0540\_Q  
0699\_X06011E  
1232\_B12470B  
S3B\_Q  
7792\_X77050A  
6192\_X61026D  
SMCJ24A\_Q

|                       |                         |                  |
|-----------------------|-------------------------|------------------|
| 74F86SCX_Q            | CD4013BCN_SC160424      | SMCJ17A_Q        |
| 74AC646SCX_Q          | NC7SZ00M5X_Q            | MMSZ5240B_Q      |
| 74LCX574MTCX_Q        | 74VHC125MTCX_Q          | MMPQ2222A_Q      |
| 74LCX543MSAX_Q        | NC7SZ14P5X_Q            | IZD4_FZIZ004A    |
| CD4051BCN_ECAA083     | NC7SZ14M5X_Q            | FDLL4448_Q       |
| 74AC191SCX_Q          | 74LVT162244MTDX_Q       | BCP53_Q          |
| 74ABT374CMTCX_Q       | NC7S08M5X_Q             | RZD4_FZRZ004A    |
| 74VHC74SJX_Q          | 74ACT32SCX_Q            | MMBF4393_Q       |
| 74LCX240WMX_Q         | 74LVQ240SCX_Q           | SS14_Q           |
| 74F00PC_Q             | 74VHC541MTCX_Q          | SMCJ85A_Q        |
| CD4013BCN_Q           | MM74HC02MX_Q            | MMBD1204_Q       |
| NC7S04P5X_QF40        | MM74HC32MX_Q            | MMBT5210_Q       |
| 74VHC132MX_Q          | 74LVTH32245GX_Q         | BAS31_Q          |
| 74ABT16374CSSCX_Q     | 74ACT04SCX_Q            | MMBF4391_Q       |
| 74AC157SJX_Q          | CD4051BCMX_SC160655     | MMBT2907A_Q      |
| 74VHC4046MX_Q         | 74VHC245MTCX_Q          | MMBT6427_Q       |
| NC7ST32P5X_Q          | NC7SP17P5X_Q            | ES2D_Q           |
| 74VHC14MTCX_QF40      | 74LCX16373MEAX_Q        | MMBT100A_Q       |
| CD4013BCN_SM62748     | MM74HC00MX_SC161318     | MMBTA13_Q        |
| 74VCX16373MTDX_Q      | MM74HC164MX_Q           | S1M_Q            |
| MM74HC08N_QF40        | 74LCX14MTCX_Q           | 7349_B73026A     |
| MM74HC14N_Q           | 74AC08SCX_Q             | MB4S_Q           |
| 74F541SJ_Q            | MM74C922WMX_Q           | BAT54S_Q         |
| MM74HC244WMX_Q        | MM74HC32MX_SF501590     | MMBD1205_Q       |
| 74AC08SCX_SF87239A    | DM74ALS05AMX_Q          | 1N4738ATR_Q      |
| NC7S14P5X_Q           | MM74HCT14MTCX_Q         | FZWZ004A_QF084   |
| 74F151ASJX_Q          | NC7S04P5X_Q             | FZXZ004A_QF084   |
| 74LVX245MTCX_Q        | 74VHC02MTCX_SF500910    | J270_Q           |
| 74F573SJX_Q           | 74LCX245MTCX_Q          | 6549_B65113B     |
| 74F112SJ_Q            | NC7WZ07P6X_Q            | MMBT2484_Q       |
| 74LCX240MTCX_Q        | 74LCX245MSAX_Q          | MMSZ4684_Q       |
| 74F138SJ_Q            | 74ACTQ541SCX_Q          | MMBD1505A_Q      |
| 74F08SJ_Q             | DM74ALS14MX_Q           | MMBFJ310_Q       |
| NC7SZ11P6X_Q          | MM74HC688WMX_SF501694   | MMSZ5239B_Q      |
| NC7S00M5X_Q           | MM74HC595MX_Q           | MMBT2222A_Q      |
| MM74HCT164MX_QF086    | 74ACT125SCX_Q           | SMBJ18A_Q        |
| 74ACT374SCX_Q         | NC7SZ86P5X_Q            | MMBD1401_Q       |
| CD4050BCN_SM62751     | NC7S08M5X_SF500951      | MMPQ3904_Q       |
| 74AC08SCX_SF501224    | NC7WZ14P6X_Q            | BAV21TR_Q        |
| 74ABT899CQCX_SF500674 | GTLP18T612MTDX_SF501624 | SMCJ75A_Q        |
| MM74HCT05MX_Q         | 74AC240SCX_Q            | 6892_X68025A     |
| 74ACT253SCX_Q         | 74F280SCX_Q             | PZTA42_Q         |
| NC7SPU04P5X_Q         | 74ACT245SCX_Q           | 0692_X06044D     |
| 74F157ASJX_Q          | NC7SZ04M5X_Q            | MMSZ5248B_Q      |
| 74F125SCX_Q           | 74LCX244MTCX_Q          | ES1D_Q           |
| 74F164APC_Q           | NC7SV08P5X_Q            | BAT54A_Q         |
| 74ACT1284MSAX_Q       | 74AC240MTCX_Q           | 7892_X78046C     |
| 74LCX08MX_QF086       | MM74HC14MX_SC162433     | 1N4148TR_Q       |
| NC7SZU04M5X_Q         | 74LCX16244MEAX_Q        | MMBFJ176_Q       |
| 74LVX3245MTCX_QF40    | 74LVX132MTCX_Q          | MMBT3904_Q       |
| 74AC74SJX_Q           | CD4013BCN_SF501688      | MMBT4403_Q       |
| 74LVTH162373MTD_Q     | NC7SZ08M5X_Q            | MMPQ2907A_Q      |
| 74F253SJX_QF042       | CD4001BCMX_SF501684     | MMBD1503_Q       |
| NC7SZ125M5X_SF500989  | DM74AS32MX_Q            | FMBM5401_SB74001 |
| CD40106BCM_Q          | 74ACQ573SCX_Q           | 4296_ST42091     |

|                      |                      |                |
|----------------------|----------------------|----------------|
| 74LVT16373MEAX_Q     | 74VHC74MTCX_SF500950 | 3999_X39044C   |
| 74ACT138PC_Q         | NC7WZ16P6X_Q         | 2K49_B2K002A   |
| MM74HC4046MX_QF40    | CD4013BCMX_SF501686  | 0592_T05116G   |
| MM74HC138MX_Q        | DM74ALS125MX_Q       | NZT660A_Q      |
| 74F374SJX_Q          | NC7SZ58P6X_Q         | MMBD1504_Q     |
| 74F151ASCX_SF86309A  | MM74HC4046MX_Q       | 0699_X06040F   |
| 74VHC595MTCX_Q       | MM74HC14MX_SC162268  | 0692_X06003C   |
| MM74HCT374WMX_Q      | 74AC00SCX_SF501638   | MMBTH81_Q      |
| 74ABT16652CMTDX_Q    | 74LCX125MTCX_Q       | 1N4736ATR_Q    |
| 74F574SJX_Q          | 74LCX821MSAX_Q       | 1292_X12398C   |
| NC7SZ125P5X_QF40     | CD4060BCMX_Q         | 3K49_FDSS517D  |
| 74LVTH125MTCX_Q      | CD4016BCMX_SF501689  | BAV70_Q        |
| 74F244SJX_Q          | NC7SZ125P5X_Q        | MMBT2369A_Q    |
| DM74ALS373WMX_Q      | NC7S14M5X_SF500948   | 7899_X78060D   |
| DM74ALS21AMX_Q       | NC7SZ08P5X_Q         | MMBD1403_Q     |
| 74AC253SCX_Q         | 74LCX74MTCX_Q        | BAV103_Q       |
| 74F04SJX_Q           | MM74HC14MX_SC162391  | MMBT3640_Q     |
| 74VHC163MTCX_QF40    | 74VHC4053MX_Q        | 6392_T63574H   |
| 74F139SCX_Q          | NC7SZ125M5X_Q        | MMBF4392_Q     |
| 74AC163SCX_Q         | NC7SZ86M5X_SF500979  | 5497_F54012A   |
| 74LVTH374MTCX_Q      | 74ACT823SCX_Q        | FJH1100_Q      |
| 74AC86SCX_Q          | NC7WZ17P6X_Q         | SMBJ12A933_Q   |
| 74F32SJX_Q           | 74LCX16244GX_Q       | MMBD4148CC_Q   |
| 74F11SCX_Q           | CD4066BCMX_SF501683  | NZT749_Q       |
| 74ABT126CSCX_Q       | 74VHC14MTCX_SF500908 | MMSD4148_Q     |
| MM74C00N_Q           | MM74HCT138MX_ECLD872 | 1049_B10086A   |
| MM74HC4060MTCX_Q     | 74VHC08MTCX_SF500909 | MMBD1203_Q     |
| 74LVX14MTCX_Q        | CD4051BCMX_SF501680  | 7449_B74043A   |
| 74F04PC_Q            | NC7WZ04P6X_Q         | MMBTA28_Q      |
| 74F74PC_Q            | 74LCX16245MEAX_Q     | 2L49_B2L003A   |
| 74AC574SJX_Q         | 74AC04SCX_SF501500   | MMBD1504A_Q    |
| 74ACT244MTCX_Q       | FDC645N_Q            | SMBJ40A_Q      |
| 74LCX06MTCX_SF501652 | FDW254P_Q            | 1092_X10042A   |
| MM74HCT573MTCX_Q     | FDS4953_Q            | PZT2222A_Q     |
| 74ACT257SCX_Q        | FDD6530A_QF080       | 8849_B88107A   |
| 74ACT02SCX_Q         | FDS6898AZ_Q          | ES3D_Q         |
| 74F374SJ_Q           | NDS8435A_Q           | NZT560A_Q      |
| MM74HC86MX_Q         | FDS6692_Q            | 2V49_B2V001A   |
| 74ACTQ244MSAX_Q      | NDT452AP_Q           | 1N4148TA_Q     |
| 74LVX00MX_Q          | FDS4465_QF40         | 2G49_B2G005A   |
| 74ACT573SCX_Q        | FDC638P_B4E005A      | FZIZ004A_QF084 |
| MM74HC4053N_Q        | SI4822DY_Q           | BAT54C_Q       |
| 74F269SCX_Q          | FDS4935A_Q           | FZRZ004A_QF084 |
| MM74HC04MX_Q         | FDW2501N_Q           | MMBD1503A_Q    |
| MM74HC74AMX_Q        | NDP6060_QF40         | MBR0520L_Q     |
| MM74HC74AMTCX_Q      | SI4450DY_Q           | KSC2982BTF_Q   |
| 74F541SJX_Q          | FDS3912_Q            | BAV102_Q       |
| MM74HC174MX_Q        | NDS8936_Q            | BAT54_Q        |
| 74LVX04MTCX_QF40     | SI4412DY_Q           | SS34_Q         |
| 74AC257SCX_Q         | FDS6986AS_Q          | 6849_B68046A   |
| 74VHCT541AMTCX_QF40  | FDC606P_Q            | 1649_B16063A   |
| MM74HC4538MX_Q       | FDD3690_Q            | 1049_B10204B   |
| NC7SZ04M5X_SF501625  | NDS9933A_QF40        | 1N4148_Q       |
| 74VCX38MX_Q          | FDS6894AZ_Q          | NZT7053_Q      |
| 74AC157SCX_Q         | FDS8947A_Q           | MMBD4148_Q     |

74VCX32374G\_Q  
CD4001BCMX\_SC162369  
74AC541PC\_Q  
74VHC123AMTCX\_QF40  
NC7SZ86M5X\_Q  
MM74HCT74MX\_Q  
74ACT161SCX\_Q  
NC7ST04M5X\_Q  
74AC240SJ\_Q  
74ABT245CMSAX\_Q  
74F269SPC\_Q  
74ACTQ16374SSCX\_Q  
74VHC123AMX\_Q  
74LCX16652MEAX\_Q  
74ACT245SJ\_Q  
MM74HC157SJX\_Q  
74ACTQ245SJX\_Q  
MM74HC541WMX\_Q  
74VHC14N\_QF015  
MM74HC4060MX\_Q  
MM74HC164N\_Q  
74ABT16244CMTDX\_QF40  
NC7S86P5X\_Q  
74VHCT244AMTCX\_Q  
MM74HCT373WMX\_Q  
74LCX16373MTDX\_Q  
74ABT541CMSAX\_Q  
74F240SJX\_Q  
MM74HCT245MTCX\_Q  
74VHC221AMX\_Q  
74F00SJ\_Q  
74F175SJ\_Q  
NC7S32P5X\_Q  
MM74HC126MX\_Q  
74F02SJ\_Q  
DM74ALS257MX\_Q  
MM74HC240WMX\_Q  
74ABT899CQCX\_Q  
MM74HC595N\_SC162507  
NC7WZ14P6X\_QF40  
74F273PC\_Q  
MM74HC165MX\_Q  
74ABT16245CMTDX\_QF40  
74VHCT04AMTCX\_Q  
74LCX16244MTDX\_Q  
74AC251SCX\_Q  
74F04SCX\_Q  
74VHCT574AMTCX\_Q  
NC7WZ125K8X\_Q  
74F08SJX\_Q  
74LVX163MTCX\_QF40  
74ACTQ244SJX\_Q  
74AC273MTCX\_Q  
74ACTQ240SJX\_Q  
74F191SJX\_Q

MTD3055V\_Q  
FDS6961A\_Q  
9L32\_B9L001B  
FDC3512\_Q  
FDR8508P\_Q  
FDD6672A\_Q  
NDS8434\_Q  
NDB6030PL\_Q  
FDS3601\_Q  
FDN358P\_Q  
FDD6512A\_Q  
NDS336P\_Q  
FDS6982S\_Q  
FDD5670\_QF40  
FDC6329L\_Q  
FDD2572\_Q  
NDB6020P\_Q  
FDS6680\_QF40  
NDS9948\_Q  
FDS6890A\_Q  
NDS0605\_Q  
FDS4953\_QF40  
SI3445DV\_Q  
FDZ7064AS  
NDT2955\_Q  
FDG329N\_Q  
RF3S49092SM9A\_Q  
NDS9435A\_Q  
FDC6306P\_Q  
FDS6982\_Q  
NDT451AN\_Q  
FDS2572\_Q  
NDS9953A\_Q  
FDS6875\_Q  
FDP7045L\_QF40  
FDU6680\_QF071  
FDV302P\_Q  
ISL9N302AS3ST\_Q  
FDC6326L\_Q  
FDS6675\_Q  
FDC6392S\_Q  
FDS4435\_Q  
FDG6321C\_Q  
FDS7764A\_Q  
SI9426DY\_Q  
FDG311N\_Q  
FDD2670\_Q  
NDS8425\_Q  
FDR6674A\_Q  
NDS356AP\_Q  
NDB5060L\_Q  
FDD6035AL\_Q  
HUF76009D3ST\_Q  
FDC6331L\_Q  
FDS4480\_Q

3G49\_B3G005A  
MMBFJ108\_Q  
MMBD1501A\_Q  
BAV99\_Q  
NZT660\_Q  
S1B\_Q  
MMBT5771\_Q  
ML6426CS1\_Q  
FMS6413CS\_Q  
ML6427CS\_Q  
FMS3818KRC\_Q  
FMS6413CSX\_Q  
FMS6410CSX\_Q  
ML6416CSX\_Q  
NC7SZ384P5X\_Q  
FST3384MTCX\_Q  
FST3125MTCX\_Q  
NC7SB3157P6X\_QF40  
FSAV331MTCX\_Q  
FST3245MTCX\_Q  
FSAV330MTCX\_Q  
FST3257MTCX\_Q  
FSA1156P6X\_QF40  
FST16211GX\_Q  
FSLV16211GX\_Q  
FST32211G\_Q  
NC7WB66K8X\_Q  
FST3125MX\_Q  
FSA266K8X\_Q  
NC7SZ66P5X\_Q  
NC7SZ66M5X\_Q  
FSTUD32450GX\_Q  
NC7SZD384M5X\_Q  
FSAL200QSCX\_Q  
NC7SZ384M5X\_Q  
NC7SB3157P6X\_Q  
NC7SB3257P6X\_Q  
FAN1086MX\_Q  
FAN1655MTF\_Q  
FAN1951D25X\_Q  
FM803SP3X\_Q  
FAN5067MX\_Q  
ILC6363CIRADJX\_Q  
ML4425CS\_Q  
FAN1582DX\_Q  
FAN1112SX\_Q  
FAN4855MTCX\_Q  
FAN1086M33X\_Q  
FAN5234MTCX\_Q  
FAN1587AM33X\_Q  
ACE1202EMX\_Q  
FM95HS01EM8X\_EMLI896  
FAN2502S25X\_Q  
FAN5240MTCX\_Q  
FAN5236QSCX\_Q

MM74HCT244WMX\_SF501631  
74F273SJX\_Q  
MM74HC393MX\_Q  
74LVX3245MTCX\_Q  
74F244MSA\_Q  
74F38SJX\_Q  
74F280SJ\_Q  
74LCX74SJX\_Q  
MM74C221N\_Q  
74AC299PC\_Q  
74ACT157SCX\_Q  
74AC244SJX\_Q  
74F04SJ\_Q  
NC7WZ08K8X\_Q  
74ACT139SCX\_Q  
DM74ALS258MX\_Q  
74F164ASCX\_Q  
74ABT244CMSAX\_Q

FDC6321C\_Q  
SI9435DY\_Q  
NDT3055\_Q  
FDS4935\_Q  
FDS6984S\_Q  
FDS4559\_Q  
FDN360P\_Q  
FDS8958A\_Q  
FDW254PZ\_Q  
SI4435DY\_Q  
FDS6672A\_Q  
FDS4675\_Q  
FDN359AN\_Q  
SI4466DY\_Q  
FDW2504P\_QF064  
SI3443DV\_Q  
SI4936DY\_Q  
FDD6530A\_Q

FAN1117AS33X\_Q  
FM95HS01EM8X\_EMLI906  
ILC6363CIR50X\_EA3E217  
FAN6555MX\_Q  
FAN2500S33X\_Q  
FAN1117ASX\_Q  
FAN5007MX\_Q  
FM95HS01EM8X\_EMLI941  
ILC6363CIR50X\_EA3E230  
ML4425CSX\_Q  
RC0431AST\_Q  
FAN1655MX\_Q  
FM95HS01EM8X\_EMLI915  
FAN1587AMX\_Q  
FAN5019MTCX\_Q  
FAN5009MX\_Q  
FAN5009MX\_SM2C205  
RV4141AMT\_Q