




China RoHS 2 - HAZARDOUS SUBSTANCES OR ELEMENTS						
Marking	Lead (Pb)	Mercury (Hg)	Cadmium (Cd)	Hexavalent Chromium (Cr (VI))	Polybrominated Biphenyls (PBB)	Polybrominated Diphenyl Ethers(PBDE)
	O	O	O	O	O	O

X: Indicates that this toxic or hazardous substance is contained in at least one of the homogeneous materials used for this part is about the limit requirement in SJ/T11363-2006.

O: Indicates that this toxic or hazardous substance is contained in all the homogeneous materials used for this part is below the limit requirement in SJ/T11363-2006.